



Production Process Photograph

Cuts Rightly in Standard



Cuts Rightly in Standard




End Portion Cutting



Hole Cutting of Assembly Part



Hole Cutting of Assembly Part



Bending of Assembly Part



Welding of Panel Conner – 1



Welding of Panel Conner – 2




Welding Portion it Trims -1



Welding Portion it Trims -2



Insulation Process - 1



Insulation Process - 2

